


# C3030-14

## Datumovka - Prázdná



\* Parametr "a" udává hloubku šipky ve vložce datumovky.



kód	D	L	d	a*	M	T
C3030-14/5	5	17	3	0,4	M3	3
C3030-14/6	6	17	3	0,4	M3	3
C3030-14/8	8	20	4	0,4	M4	5
C3030-14/10	10	20	5	0,4	M5	5
C3030-14/12	12	25	6	0,6	M6	6