


C2040

Lícovaný šroub, ISO7379



| kód | D | L | d | D1 | l | k | s | t |
|-----------------|----|----|-----|----|-----|-----|---|---|
| C2040/6x10-M5 | 6 | 10 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/6x12-M5 | 6 | 12 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/6x16-M5 | 6 | 16 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/6x20-M5 | 6 | 20 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/6x25-M5 | 6 | 25 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/6x30-M5 | 6 | 30 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/6x40-M5 | 6 | 40 | M5 | 10 | 9,5 | 4,5 | 3 | 2 |
| C2040/8x12-M6 | 8 | 12 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/8x16-M6 | 8 | 16 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/8x20-M6 | 8 | 20 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/8x25-M6 | 8 | 25 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/8x30-M6 | 8 | 30 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/8x40-M6 | 8 | 40 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/8x50-M6 | 8 | 50 | M6 | 13 | 11 | 5,5 | 4 | 3 |
| C2040/10x16-M8 | 10 | 16 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x20-M8 | 10 | 20 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x25-M8 | 10 | 25 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x30-M8 | 10 | 30 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x40-M8 | 10 | 40 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x50-M8 | 10 | 50 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x60-M8 | 10 | 60 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x70-M8 | 10 | 70 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/10x80-M8 | 10 | 80 | M8 | 16 | 13 | 7 | 5 | 4 |
| C2040/12x16-M10 | 12 | 16 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x20-M10 | 12 | 20 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x25-M10 | 12 | 25 | M10 | 18 | 16 | 9 | 6 | 5 |

| kód | D | L | d | D1 | l | k | s | t |
|------------------|----|-----|-----|----|----|----|----|----|
| C2040/12x30-M10 | 12 | 30 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x40-M10 | 12 | 40 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x50-M10 | 12 | 50 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x60-M10 | 12 | 60 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x70-M10 | 12 | 70 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x80-M10 | 12 | 80 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x90-M10 | 12 | 90 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/12x100-M10 | 12 | 100 | M10 | 18 | 16 | 9 | 6 | 5 |
| C2040/16x30-M12 | 16 | 30 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x40-M12 | 16 | 40 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x50-M12 | 16 | 50 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x60-M12 | 16 | 60 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x70-M12 | 16 | 70 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x80-M12 | 16 | 80 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x90-M12 | 16 | 90 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x100-M12 | 16 | 100 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/16x120-M12 | 16 | 120 | M12 | 24 | 18 | 11 | 8 | 6 |
| C2040/20x40-M16 | 20 | 40 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x50-M16 | 20 | 50 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x60-M16 | 20 | 60 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x70-M16 | 20 | 70 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x80-M16 | 20 | 80 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x90-M16 | 20 | 90 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x100-M16 | 20 | 100 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/20x120-M16 | 20 | 120 | M16 | 30 | 22 | 14 | 10 | 8 |
| C2040/24x50-M20 | 24 | 50 | M20 | 36 | 27 | 16 | 12 | 10 |
| C2040/24x60-M20 | 24 | 60 | M20 | 36 | 27 | 16 | 12 | 10 |
| C2040/24x70-M20 | 24 | 70 | M20 | 36 | 27 | 16 | 12 | 10 |
| C2040/24x80-M20 | 24 | 80 | M20 | 36 | 27 | 16 | 12 | 10 |
| C2040/24x90-M20 | 24 | 90 | M20 | 36 | 27 | 16 | 12 | 10 |
| C2040/24x100-M20 | 24 | 100 | M20 | 36 | 27 | 16 | 12 | 10 |
| C2040/24x120-M20 | 24 | 120 | M20 | 36 | 27 | 16 | 12 | 10 |