


C2714

Nástrojová tlačná pružina, Silné zatížení (červená)



* Parametr "R [N/mm]" je síla potřebná ke stlačení pružiny o 1 mm.



kód	D	d	L0	R [N/mm]*
C2714/10x25	10	5	25	22,1
C2714/10x32	10	5	32	17,5
C2714/10x38	10	5	38	17,1
C2714/10x44	10	5	44	15
C2714/10x51	10	5	51	12,8
C2714/10x64	10	5	64	10,7
C2714/10x76	10	5	76	7,5
C2714/10x305	10	5	305	2,1
C2714/12,5x25	12,5	6,3	25	42,1
C2714/12,5x32	12,5	6,3	32	33,2
C2714/12,5x38	12,5	6,3	38	29,3
C2714/12,5x44	12,5	6,3	44	24,6
C2714/12,5x51	12,5	6,3	51	19,6
C2714/12,5x64	12,5	6,3	64	15
C2714/12,5x76	12,5	6,3	76	13,2
C2714/12,5x89	12,5	6,3	89	11,4
C2714/12,5x102	12,5	6,3	102	8,4
C2714/12,5x305	12,5	6,3	305	2,8
C2714/16x25	16	8	25	75,7
C2714/16x32	16	8	32	52,8
C2714/16x38	16	8	38	48,5
C2714/16x44	16	8	44	42,8
C2714/16x51	16	8	51	37,1
C2714/16x64	16	8	64	30,3

kód	D	d	L0	R [N/mm]*
C2714/16x76	16	8	76	25,7
C2714/16x89	16	8	89	21,7
C2714/16x102	16	8	102	19,3
C2714/16x115	16	8	115	15,7
C2714/16x305	16	8	305	7,1
C2714/20x25	20	10	25	216
C2714/20x32	20	10	32	168
C2714/20x38	20	10	38	129
C2714/20x44	20	10	44	112
C2714/20x51	20	10	51	94
C2714/20x64	20	10	64	72,1
C2714/20x76	20	10	76	59,7
C2714/20x89	20	10	89	50,5
C2714/20x102	20	10	102	44,2
C2714/20x115	20	10	115	38,4
C2714/20x127	20	10	127	34,1
C2714/20x139	20	10	139	31
C2714/20x152	20	10	152	28,2
C2714/20x305	20	10	305	15
C2714/25x25	25	12,5	25	375
C2714/25x32	25	12,5	32	297
C2714/25x38	25	12,5	38	219
C2714/25x44	25	12,5	44	187
C2714/25x51	25	12,5	51	156
C2714/25x64	25	12,5	64	123
C2714/25x76	25	12,5	76	99
C2714/25x89	25	12,5	89	84
C2714/25x102	25	12,5	102	73
C2714/25x115	25	12,5	115	65
C2714/25x127	25	12,5	127	57,7
C2714/25x139	25	12,5	139	52,7
C2714/25x152	25	12,5	152	47,8
C2714/25x178	25	12,5	178	41
C2714/25x203	25	12,5	203	35,8
C2714/25x305	25	12,5	305	22,9
C2714/32x38	32	16	38	338
C2714/32x44	32	16	44	324
C2714/32x51	32	16	51	272
C2714/32x64	32	16	64	212
C2714/32x76	32	16	76	172
C2714/32x89	32	16	89	141

kód	D	d	L0	R [N/mm]*
C2714/32x102	32	16	102	122
C2714/32x115	32	16	115	107
C2714/32x127	32	16	127	93
C2714/32x139	32	16	139	86
C2714/32x152	32	16	152	78
C2714/32x178	32	16	178	67,2
C2714/32x203	32	16	203	59,1
C2714/32x254	32	16	254	46,4
C2714/32x305	32	16	305	38
C2714/40x51	40	20	51	350
C2714/40x64	40	20	64	369
C2714/40x76	40	20	76	219
C2714/40x89	40	20	89	190
C2714/40x102	40	20	102	163
C2714/40x115	40	20	115	142
C2714/40x127	40	20	127	128
C2714/40x139	40	20	139	115
C2714/40x152	40	20	152	105
C2714/40x178	40	20	178	89
C2714/40x203	40	20	203	77
C2714/40x254	40	20	254	61
C2714/40x305	40	20	305	51
C2714/50x64	50	25	64	413
C2714/50x76	50	25	76	339
C2714/50x89	50	25	89	288
C2714/50x102	50	25	102	245
C2714/50x115	50	25	115	215
C2714/50x127	50	25	127	192
C2714/50x139	50	25	139	168
C2714/50x152	50	25	152	154
C2714/50x178	50	25	178	134
C2714/50x203	50	25	203	117
C2714/50x254	50	25	254	89
C2714/50x305	50	25	305	73
C2714/63x76	63	38	76	618
C2714/63x89	63	38	89	515
C2714/63x102	63	38	102	438
C2714/63x115	63	38	115	370
C2714/63x127	63	38	127	333
C2714/63x152	63	38	152	269
C2714/63x178	63	38	178	226

kód	D	d	L0	R [N/mm]*
C2714/63x203	63	38	203	198
C2714/63x254	63	38	254	155
C2714/63x305	63	38	305	128