


# C2714

## Nástrojová tlačná pružina, Silné zatížení (červená)



\* Parametr "R [N/mm]" je síla potřebná ke stlačení pružiny o 1 mm.



| kód            | D    | d   | L0  | R [N/mm]* |
|----------------|------|-----|-----|-----------|
| C2714/10x25    | 10   | 5   | 25  | 22,1      |
| C2714/10x32    | 10   | 5   | 32  | 17,5      |
| C2714/10x38    | 10   | 5   | 38  | 17,1      |
| C2714/10x44    | 10   | 5   | 44  | 15        |
| C2714/10x51    | 10   | 5   | 51  | 12,8      |
| C2714/10x64    | 10   | 5   | 64  | 10,7      |
| C2714/10x76    | 10   | 5   | 76  | 7,5       |
| C2714/10x305   | 10   | 5   | 305 | 2,1       |
| C2714/12,5x25  | 12,5 | 6,3 | 25  | 42,1      |
| C2714/12,5x32  | 12,5 | 6,3 | 32  | 33,2      |
| C2714/12,5x38  | 12,5 | 6,3 | 38  | 29,3      |
| C2714/12,5x44  | 12,5 | 6,3 | 44  | 24,6      |
| C2714/12,5x51  | 12,5 | 6,3 | 51  | 19,6      |
| C2714/12,5x64  | 12,5 | 6,3 | 64  | 15        |
| C2714/12,5x76  | 12,5 | 6,3 | 76  | 13,2      |
| C2714/12,5x89  | 12,5 | 6,3 | 89  | 11,4      |
| C2714/12,5x102 | 12,5 | 6,3 | 102 | 8,4       |
| C2714/12,5x305 | 12,5 | 6,3 | 305 | 2,8       |
| C2714/16x25    | 16   | 8   | 25  | 75,7      |
| C2714/16x32    | 16   | 8   | 32  | 52,8      |
| C2714/16x38    | 16   | 8   | 38  | 48,5      |
| C2714/16x44    | 16   | 8   | 44  | 42,8      |
| C2714/16x51    | 16   | 8   | 51  | 37,1      |
| C2714/16x64    | 16   | 8   | 64  | 30,3      |

| kód          | D  | d    | L0  | R [N/mm]* |
|--------------|----|------|-----|-----------|
| C2714/16x76  | 16 | 8    | 76  | 25,7      |
| C2714/16x89  | 16 | 8    | 89  | 21,7      |
| C2714/16x102 | 16 | 8    | 102 | 19,3      |
| C2714/16x115 | 16 | 8    | 115 | 15,7      |
| C2714/16x305 | 16 | 8    | 305 | 7,1       |
| C2714/20x25  | 20 | 10   | 25  | 216       |
| C2714/20x32  | 20 | 10   | 32  | 168       |
| C2714/20x38  | 20 | 10   | 38  | 129       |
| C2714/20x44  | 20 | 10   | 44  | 112       |
| C2714/20x51  | 20 | 10   | 51  | 94        |
| C2714/20x64  | 20 | 10   | 64  | 72,1      |
| C2714/20x76  | 20 | 10   | 76  | 59,7      |
| C2714/20x89  | 20 | 10   | 89  | 50,5      |
| C2714/20x102 | 20 | 10   | 102 | 44,2      |
| C2714/20x115 | 20 | 10   | 115 | 38,4      |
| C2714/20x127 | 20 | 10   | 127 | 34,1      |
| C2714/20x139 | 20 | 10   | 139 | 31        |
| C2714/20x152 | 20 | 10   | 152 | 28,2      |
| C2714/20x305 | 20 | 10   | 305 | 15        |
| C2714/25x25  | 25 | 12,5 | 25  | 375       |
| C2714/25x32  | 25 | 12,5 | 32  | 297       |
| C2714/25x38  | 25 | 12,5 | 38  | 219       |
| C2714/25x44  | 25 | 12,5 | 44  | 187       |
| C2714/25x51  | 25 | 12,5 | 51  | 156       |
| C2714/25x64  | 25 | 12,5 | 64  | 123       |
| C2714/25x76  | 25 | 12,5 | 76  | 99        |
| C2714/25x89  | 25 | 12,5 | 89  | 84        |
| C2714/25x102 | 25 | 12,5 | 102 | 73        |
| C2714/25x115 | 25 | 12,5 | 115 | 65        |
| C2714/25x127 | 25 | 12,5 | 127 | 57,7      |
| C2714/25x139 | 25 | 12,5 | 139 | 52,7      |
| C2714/25x152 | 25 | 12,5 | 152 | 47,8      |
| C2714/25x178 | 25 | 12,5 | 178 | 41        |
| C2714/25x203 | 25 | 12,5 | 203 | 35,8      |
| C2714/25x305 | 25 | 12,5 | 305 | 22,9      |
| C2714/32x38  | 32 | 16   | 38  | 338       |
| C2714/32x44  | 32 | 16   | 44  | 324       |
| C2714/32x51  | 32 | 16   | 51  | 272       |
| C2714/32x64  | 32 | 16   | 64  | 212       |
| C2714/32x76  | 32 | 16   | 76  | 172       |
| C2714/32x89  | 32 | 16   | 89  | 141       |

| kód          | D  | d  | L0  | R [N/mm]* |
|--------------|----|----|-----|-----------|
| C2714/32x102 | 32 | 16 | 102 | 122       |
| C2714/32x115 | 32 | 16 | 115 | 107       |
| C2714/32x127 | 32 | 16 | 127 | 93        |
| C2714/32x139 | 32 | 16 | 139 | 86        |
| C2714/32x152 | 32 | 16 | 152 | 78        |
| C2714/32x178 | 32 | 16 | 178 | 67,2      |
| C2714/32x203 | 32 | 16 | 203 | 59,1      |
| C2714/32x254 | 32 | 16 | 254 | 46,4      |
| C2714/32x305 | 32 | 16 | 305 | 38        |
| C2714/40x51  | 40 | 20 | 51  | 350       |
| C2714/40x64  | 40 | 20 | 64  | 369       |
| C2714/40x76  | 40 | 20 | 76  | 219       |
| C2714/40x89  | 40 | 20 | 89  | 190       |
| C2714/40x102 | 40 | 20 | 102 | 163       |
| C2714/40x115 | 40 | 20 | 115 | 142       |
| C2714/40x127 | 40 | 20 | 127 | 128       |
| C2714/40x139 | 40 | 20 | 139 | 115       |
| C2714/40x152 | 40 | 20 | 152 | 105       |
| C2714/40x178 | 40 | 20 | 178 | 89        |
| C2714/40x203 | 40 | 20 | 203 | 77        |
| C2714/40x254 | 40 | 20 | 254 | 61        |
| C2714/40x305 | 40 | 20 | 305 | 51        |
| C2714/50x64  | 50 | 25 | 64  | 413       |
| C2714/50x76  | 50 | 25 | 76  | 339       |
| C2714/50x89  | 50 | 25 | 89  | 288       |
| C2714/50x102 | 50 | 25 | 102 | 245       |
| C2714/50x115 | 50 | 25 | 115 | 215       |
| C2714/50x127 | 50 | 25 | 127 | 192       |
| C2714/50x139 | 50 | 25 | 139 | 168       |
| C2714/50x152 | 50 | 25 | 152 | 154       |
| C2714/50x178 | 50 | 25 | 178 | 134       |
| C2714/50x203 | 50 | 25 | 203 | 117       |
| C2714/50x254 | 50 | 25 | 254 | 89        |
| C2714/50x305 | 50 | 25 | 305 | 73        |
| C2714/63x76  | 63 | 38 | 76  | 618       |
| C2714/63x89  | 63 | 38 | 89  | 515       |
| C2714/63x102 | 63 | 38 | 102 | 438       |
| C2714/63x115 | 63 | 38 | 115 | 370       |
| C2714/63x127 | 63 | 38 | 127 | 333       |
| C2714/63x152 | 63 | 38 | 152 | 269       |
| C2714/63x178 | 63 | 38 | 178 | 226       |

| kód          | D  | d  | L0  | R [N/mm]* |
|--------------|----|----|-----|-----------|
| C2714/63x203 | 63 | 38 | 203 | 198       |
| C2714/63x254 | 63 | 38 | 254 | 155       |
| C2714/63x305 | 63 | 38 | 305 | 128       |