


# C2120

## Transportní pojistka



Transportní pojistka bezpečně zajistí formu během manipulace.



kód	A	B	C	D	E	F	G	R
<b>C2120/50</b>	50	12	20	30	14	M6	M6	30
<b>C2120/63</b>	63	16	25	38	17	M8	M8	38
<b>C2120/80</b>	80	20	32	48	20	M10	M10	48