


# C2110

## Upínací stopka



kód	d1	d2	d3	l1	l2	S	l3	l4	l5	R
<b>C2110/20x28</b>	20	M20x1,5	25	40	28	14	14	17	4	6
<b>C2110/25x32</b>	25	M24x2	32	45	32	19	16	22	6	6
<b>C2110/32x37</b>	32	M30x2	40	50	37	24	17	27	8	8
<b>C2110/40x53</b>	40	M42x2	50	72	53	32	28	27	8	12
<b>C2110/50x56</b>	50	M48x2	63	80	56	41	28	27	8	12