


# C5104

## Vodící sloupek h4 se středícím nákrůžkem



| kód          | d  | L   | d2 | L1 | L2 | M  | D  | D5 | D6 |
|--------------|----|-----|----|----|----|----|----|----|----|
| C5104/20x100 | 20 | 100 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/20x112 | 20 | 112 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/20x125 | 20 | 125 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/20x140 | 20 | 140 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/20x160 | 20 | 160 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/20x180 | 20 | 180 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/20x200 | 20 | 200 | 25 | 23 | 4  | M8 | 27 | 36 | 39 |
| C5104/25x100 | 25 | 100 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x112 | 25 | 112 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x125 | 25 | 125 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x140 | 25 | 140 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x160 | 25 | 160 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x180 | 25 | 180 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x200 | 25 | 200 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x224 | 25 | 224 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/25x250 | 25 | 250 | 32 | 30 | 6  | M8 | 34 | 43 | 44 |
| C5104/32x112 | 32 | 112 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x125 | 32 | 125 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x140 | 32 | 140 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x160 | 32 | 160 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x180 | 32 | 180 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x200 | 32 | 200 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x224 | 32 | 224 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |
| C5104/32x250 | 32 | 250 | 40 | 37 | 6  | M8 | 42 | 51 | 51 |

| Kód          | d  | L   | d2 | L1 | L2 | M   | D  | D5  | D6  |
|--------------|----|-----|----|----|----|-----|----|-----|-----|
| C5104/32x280 | 32 | 280 | 40 | 37 | 6  | M8  | 42 | 51  | 51  |
| C5104/32x315 | 32 | 315 | 40 | 37 | 6  | M8  | 42 | 51  | 51  |
| C5104/40x125 | 40 | 125 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x140 | 40 | 140 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x160 | 40 | 160 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x180 | 40 | 180 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x200 | 40 | 200 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x224 | 40 | 224 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x250 | 40 | 250 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x280 | 40 | 280 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x315 | 40 | 315 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/40x355 | 40 | 355 | 50 | 37 | 6  | M8  | 52 | 61  | 59  |
| C5104/50x140 | 50 | 140 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x160 | 50 | 160 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x180 | 50 | 180 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x200 | 50 | 200 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x224 | 50 | 224 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x250 | 50 | 250 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x280 | 50 | 280 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x315 | 50 | 315 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x355 | 50 | 355 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/50x400 | 50 | 400 | 63 | 47 | 8  | M8  | 62 | 74  | 72  |
| C5104/63x160 | 63 | 160 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x180 | 63 | 180 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x200 | 63 | 200 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x224 | 63 | 224 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x250 | 63 | 250 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x280 | 63 | 280 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x315 | 63 | 315 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x355 | 63 | 355 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/63x400 | 63 | 400 | 80 | 47 | 8  | M8  | 72 | 91  | 89  |
| C5104/80x200 | 80 | 200 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |
| C5104/80x224 | 80 | 224 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |
| C5104/80x250 | 80 | 250 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |
| C5104/80x280 | 80 | 280 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |
| C5104/80x315 | 80 | 315 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |
| C5104/80x355 | 80 | 355 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |
| C5104/80x400 | 80 | 400 | 95 | 60 | 8  | M12 | 95 | 106 | 109 |